Measure the inside diameter, thickness of both areas, and outside diameter minus the gear teeth. Measure the inside and outside length, width, height, as well as the material thickness. Measure the longest and shortest lengths of the rod as well as the diameter.

Identify this socket cap screw.

Identify this hex bolt.

Measure the 3 major dimensions of the SSD without the rubber spacer.

De Co


FW; ÖZHD

Intel[®]

CE3

6

Measure the every possible dimension of this cable rack including angles and material.



Measure the hole diameters, distances between the holes, and distances from the edge of the board. Measure the overall dimensions of the board.